

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:													
Lined MSWLF	LCID		YW	Transfer		Compost		SLAS	X	COUNTY: Iredell			
Closed MSWLF	HHW		White goods	Incin		T&P		FIRM		PERMIT NO.: SLAS-49-02			
CDLF	Tire T&P / Collection		Tire Monofill	Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE			

Date of Site Inspection: 11/19/2015 Date of Last Inspection: 11/19/2014

FACILITY NAME AND ADDRESS:

Lentz Septic Tank Service, Inc. 528 Sloans Mill Road Olin, North Carolina 28660

GPS COORDINATES: N: 35.98209° W: 80.84467°

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Keith Lentz

Telephone: (704) 876-1834

Email address: keith@lentzseptic.com

FACILITY CONTACT ADDRESS:

418 Lentz Road Statesville, NC 28625

PARTICIPANTS:

Troy Harrison, NC Solid Waste Section Keith Lentz, Lentz Septic Tank Service, Inc.

STATUS OF PERMIT:

Active

Issued: 6/2/2014 Expires: 12/16/2018

PURPOSE OF SITE VISIT:

Routine Inspection Annual Soil Sampling

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS:

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1. All photographs were taken by Troy Harrison on November 19, 2015.
- 2. The Septage Land Application Site consists of Field 1 (13.8 acres), Field 2 (18.6 acres) and Field 3 (12.6 acres).
- 3. The site is permitted for land application of domestic septage and grease trap pumpings.
- 4. The site had accessible all-weather roads to the septage land application field covered under the permit.
- 5. Appropriate signage was displayed at the site.
- 6. All fields had disposal area boundaries that were well delineated with permanent markers which corresponded to the site map.
- 7. All septage discharges appear to have been made within the disposal area boundary. Fields 2 and 2 appeared to be well maintained with a good crop of fescue. Field 3 appeared to be well maintained with recent reseeding of bare spots.



Field 1 (foreground) and Field 2 (background)

- 8. No evidence of standing liquid or pooled waste was observed.
- 9. No objectionable odors were observed.
- 10. The nutrient management plan appears to have been followed on all fields.
- 11. Site logs were not reviewed at this time.
- 12. Soil samples were collected from the field. The check for soil sampling was received.

Please contact me if you have any questions or concerns regarding this inspection report.

Troy Harrison
Environmental Senior Specialist

Regional Representative

Sent on: 1/26/2016	X	Email		Hand delivery		US Mail		Certified No. [_]
--------------------	---	-------	--	---------------	--	---------	--	-------------------

Copies: Tony Gallagher, Composting & Land Application Branch Head Michelle Sclafani, Composting & Land Application Branch Connie Wylie, Composting & Land Application Branch